

ABSTRACT

Name of work :-

repairs to track roller & Idler assembly of Tata hitachi 220 Ex. Sr no 305

Sr No	Particulars	Qty	Rate	Amount
1	repairs to track roller & Idler assembly of Tata hitachi 220 Ex. Sr no 305			
	cost of spare parts	1	38567	38567 ✓
	cost of labour	1	2990	2990 ✓
			Total	41557 ✓
			add 18% GST	7480.3 ✓
			Grand Total	49037.3 ✓
			Say	49037 ✓

A. Lingappa

A.E.II

Mechanical subdivision No. 3,
Osmanabad

Isaiah

Deputy Engineer

Mechanical subdivision No. 3,
Osmanabad

[Signature]
Deputy Engineer
Osmanabad


MEASUREMENT

Name of work :-

repairs to track roller & Idler assembly of Tata hitachi 220 Ex. Sr no 305


Rate Analysis

Sr No	Particulars	Qty	Rate	Amount
1	replacing and fitting following damaged spares			
1.1	TD03657 track roller assembly	3	12283	36849 ✓
1.2	TD02713 idler bush	2	859	1718 ✓
2	labour charges			
2.1	track roller removing & refitting to machine	3	492	1476 ✓
2.2	removing and refitting idler assembly	1	1514	1514 ✓
			Total	41557 ✓
			add 18% GST	7480.3 ✓
			Grand Total	49037.3 ✓
			Say	49037 ✓



A.E.II

Mechanical subdivision No. 3,
Osmanabad



Deputy Engineer

Mechanical subdivision No. 3,
Osmanabad