


Name of Work : Repairs to clutch Assembly, Leaf Assembly of Tata Tipper MH 20 CU 208.

Sr. No.	Description	Qty	Unit	Rate	Amount
Repairs to clutch Assembly, Leaf Assembly of Tata Tipper MH 20 CU 208.					
A	Cost of Spare				
1	27632520011	Clutch Disc	1	No	
2	275425400118	Clutch Release Bearing	1	No	
3	263232400115	First Leaf	2	No	
4	263232407138	Fifth Leaf	1	No	
5	263232407140	Severnth Leaf	2	No	
6	263232407137	Fourth Leaf	2	No	
7	3523250530	Shackle Pin	4	No	
8	257532503401	Bush Spring Shackle	4	No	
9	263232403203	Center Bolt	2	No	
10	263232407142	Nineth Leaf	2	No	
Total A:					
B	Cost of Labour Charges:				
1	C/01	Clutch unit Complete dismantlin, cleaning, checking,overhauling by replacin necessary parts	1	Job	
2	C/01	Gear box removing by removing related assly and refitting after repairs	1	Job	
3	SU/02	Rear spring leaf assly. Removing, dismantling, recambering and refitting / A	2	Job	
Total B:					

Note: Mention the quoted rates are of inclusive GST charges or exclusive GST charges clearly.



Executive Engineer
Mechanical Division, Osmanabad

