

# Work Details

Name of work : Case 770 Loader Backhoe No. MH24 AJ7847

| Sr. No.   | Part Details |  | Qty/Unit |     | Rate | Total |
|---|--------------|--|----------|-----|------|-------|
|   | Part Number  | Description  |          |     |      |       |
| Repairs & reconditioning of Bucket Assembly of CASE 770 Loader Backhoe No. MH24-AJ-7847 by Reconditioning of bucket by removing damaged tooth, adapter by gas cutting and fitting new one by welding. Hard facing of bucket Replacing damaged teeth point & side cutter with new parts as per OEM specification etc complete. |              |  |          |     |      |       |
| <b>A Providing &amp; fitting following spares as per OEM</b>  |              |  |          |     |      |       |
| 1   | 47792971     | CENTER TOOTH-BUCKET PAINTED  | 3        | No. |      |       |
| 2   | 47800694     | SIDE CUTTING TOOTH LH PAINTED  | 1        | No. |      |       |
| 3   | 47800695     | SIDE CUTTING TOOTH RH PAINTED  | 1        | No. |      |       |
| 4   | 47641245     | BOLT   | 10       | No. |      |       |
| 5   | 412398       | BOLT   | 4        | No. |      |       |
| 6   | 47634533     | WASHER   | 10       | No. |      |       |
| 7   | 832-10416    | NUT  | 14       | No. |      |       |
| 8   | BU3460021    | SQUARE HOLE WASHER 40 18 3 .15   | 10       | No. |      |       |
| 9   | BU0124021    | CUTTING EDGE   | 1        | No. |      |       |
| 10  | BU8990048    | LINK/A-BACKHOE BUCKET  | 1        | No. |      |       |
| 11  | 47546538     | PIN ASSY-BACKJOE BUCKET ATTACHING  | 1        | No. |      |       |
| 12  | BU2720145    | PIN B/H BKT CYL(851)   | 1        | No. |      |       |
| 13  | 85819062     | HOSE SIDE SHIFT  | 1        | No. |      |       |
| <b>Total of Spares Rs.</b>  |              |  |          |     |      |       |
| <b>B Labour Chagges</b>   |              |  |          |     |      |       |
| 1   | A/20         | Dismantalling & refitting Bucket assy.   | 1        | Job |      |       |
| 2   | A/27         | Reconditioning of bucket by removing damaged Cutting Edge plates by gas cutting and strengthening by fitting new plates by welding | 1        | Job |      |       |
| 3   | A/13         | Repairs to Bucket by replacing the teeth excavators / no   | 3        | Job |      |       |
| 4   | A/15         | Replacing side cutter of bucket / No.  | 2        | Job |      |       |
| 5   | H/06         | Removing and refitting high pressure hose assly  | 1        | Job |      |       |
| <b>Total of Labour Rs.</b>  |              |  |          |     |      |       |
| <b>Total ( Spares + Labour ) Rs :</b>   |              |  |          |     |      |       |
| <b>CGST 9%</b>  |              |  |          |     |      |       |
| <b>SGST 9%</b>  |              |  |          |     |      |       |
| <b>Grand Total Rs :</b>   |              |  |          |     |      |       |
| <b>Round Off Rs :</b>   |              |  |          |     |      |       |

  
 ( G.S. Giram )  
**Deputy Engineer**  
 Mechanical Subdivision (LTP),  
 Latur