



## Measurement

Name of work : Repair & reconditioning Bucket cylinder assly of Tata Hitachi 120H no. 52475 ✓

Sr. No.	Description	Qty	unit	rate	Amount
1	2	3	4	5	9
	Repair & reconditioning Bucket cylinder assly of Tata Hitachi 120H no. 52475				
A 1)	Removing Bucket cylinder assly from machine and refitting after repairs to machine (H/08)	1 ✓	job	3598 ✓	3598 ✓
2	Removing and refitting non hidden High pressure hoses & main piping (H/08)	2 ✓	job	636 ✓	1272 ✓
3	Dismantling cylinder assly cleaning replacing seal service kit (H/09)	1 ✓	job	1704 ✓	1704 ✓
B	Providing & fitting following spares as per OEM specification & part No. given below				
1	TC01377/37 seal kit ✓	1 ✓	no	17523 ✓	17523 ✓
2	TC01377/4 piston rod nut ✓	1 ✓	no	2374 ✓	2374 ✓
3	4333699 hose ✓	1 ✓	No	11946 ✓	11946 ✓
4	TC01377/9 pipse S/A ✓	1 ✓	no	3795 ✓	3795 ✓
Total					42212 ✓
GST 18 %					7598 ✓
Total					49810 ✓

  
 B.V. Satpute  
 ( Section Engineer)

  
 Deputy Engineer  
 Mechanical Sub Division No.3