Name of Work: Repairs to JCB JS-140 Excavator No. 2439384 by way of supplying and fitting Hose, Fan,

Water Pump, Turbocharger, Teeth, Pin & Washer etc

Sr. No.	Description	Qty	Unit	Rate	Amount
	Repairs to JCB JS-140 Excavator No. 2439384 by way of supplying and fitting Hose, Fan, Water Pump, Turbocharger, Teeth, Pin & Washer etc as per OEM Specification & part number given below				
A	Cost of Spare Charges:				
	transfer management	1	No		
1	KMV0932 - Hose	1	INU		a) R
2	4080727 - Fan	1	No	2\39	
3	332/Y3313 - Water Pump	1	No	(I/S	
4	4035721 - Turbocharger	1	No		
5	229/01302 - Tooth	4	Nos		
6	229/01303 - Lock Washer (Alt-229/01303)	3	Nos		
7	229/01304 - Lock Pin (JS130, 330)	4	Nos		亚新 斯
	जीत क्यांना अर्था है स्थानिक स	E No 1		Total A:	2 stareful
В	Cost of Labour Charges:				
1	Repairs to Bucket by replacing the Teeth for excavators /	4	Job	randin);	.3
2	Silencer / muffler repairing by removing, cleaning and refitting with welding work	1	Job	er ny tenin Prikipyo	5
3	Replacing Water Pump Assembly	1	Job	,6619B	
4	Removing Radiator, Fan, Guard etc and refitting to machine after repairs	1	Job	मा है । । । भारती की	. š
5	Removing & refitting High Pressure Hose Assembly	1	Job	18 (5 180) 8 (5) (8) (8)	. P
1				Total B	

Note: Mention the quoted rates are of enclusive GST charges or exclusive GST charges clearly.

Executive Engineer

Mechanical Division, Osmanabad

The makes