


Name of Work : Repairs To Water Pump Assly of Tata Hitachi 120 H  
No. 52466

Sr.No	Description of Job	Qty.
	Repairs To Water Pump Assly of Tata Hitachi 120 H No. 52466	
A	Cost of Spare	
1	4440813 - Fan Belt	1 No.
2	897253-0281 - Pump assly water pump	1 No.
B	Cost of Labour	
1	Radiator chock up removing by cleaning all the tubes, soldering the tubes with top & bottomremoving and refitting.	1 Job

  
Deputy Engineer  
Mechanical Sub division No. 3  
Osmanabad