

WORK DETAILS

Name of work : Repairing to travel device (RH) side for TATA Hitachi Ex350-0402

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repairs to TATA Hitachi Ex350-0402 by way of supplying & fitting following spares as per OEM Specification & part number given below. (Repairing to travel device (RH))					
A	Providing & fitting following spares as per OEM Specification					
1	4066695	Seal Group	1	No.		
2	4371402	Bearing Needle	4	No.		
B	LABOUR CHARGES					
1	Overhauling of Ttavel motors by dismantling, cleaning and inspection of parts, reassembling etc.		1	Job		
GST 18%						
Total Rs						



**Deputy Engineer
Mechanical Subdivision, Latur**