

WORK DETAILS

Name of work : Repairs to Hydraulic pum assly. of TATA Hitachi 120 H No.52473

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repairs to Hydraulic pum assly. of TATA Hitachi 120 H No.52473 by way Dismenraling Hydraulic pump assly.and inspecting, Replacing damaged spares as mentioned below &assembling pump by using new spares as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	2042059	Rotor	1	No.		
2	2044793	Plate valve	1	No.		
3	4355272	Baring needle	1	No.		
4	4463047	Seal Kit	1	No.		
B	LABOUR CHARGES					
1	Removing Hydraulic pump from mahine and Fitting after		1	Job		
GST 18%						
Total Rs						



**Deputy Engineer
Mechanical Subdivision, Latur**