

ENQUIRY

Name of work : **Repair & Reconditioning Both Sides Recoil
Cylinder Assly of JCB JS 140 No 2439386**

Sr. No.	Part Details		Qty.		Remark
	Part Number	Description			
	Repair & Reconditioning Both Sides Recoil Cylinder Assly of JCB JS 140 No 2439386 by removing the cylinder assly from machine, checking and removing unservicable parts and removing hyd. hoses & replacing by new spares as per OEM Specification				
A	Providing & fitting following spares as per OEM Specification				
a	JNA0237	Rod	2	No	
b	JNA0239	Seal	1	No	
c	JNA0238	Ring	2	No	
d	1316/0403Z	Screw	4	No	
e	JRA0233	Valve Check	2	No	
e	624/80025	Hose	3	No	
B	Cost of Labour Charges				
1	Dis-nantling Track chain by removing Master Pin / Master Link bolts.(UC/01)		1	Job	
2	Repairs to recoil cylinder by replacing oil seal. Complete job(UC/12)		1	Job	
3	Reassembling of track chain & fitting of master pin by hydraulic press.(UC/15)		1	Job	
4	Removing & refitting hidden high pressure hose assy.(H/06)		3	Job	


Deputy Engineer
Mech. Sub Division (L.T.P)
Latur