


Work Details

Name of work : Repair to Main Piping Of Tata Hitachi 120 H No.52474

Sr. No.	Description	Part No	Qty	Unit	Rate	Amount
1	2	3	4	5	6	7
	Repair to Main Piping Of Tata Hitachi 120 H No.52474 by repairs to following spares parts as per OEM Specification of given below.					
A	Spare Parts					
1	4333700	HOSE	1	No		
2	4510173	FLANGE;SPLIT 001/2-S	8	No		
3	4510167	O-RING 1B15	4	No		
4	4333699	HOSE	1	No		
5	A853144	ADAPTER;S	2	No		
6	4203130	HOSE	1	No		
7	4203129	HOSE	1	No		
8	M340825	BOLT;SOCKET M08X025.	16	No		
Total A						
B	Labour Charges					
1	Removing & refitting high pressure hose assly. H/06		4	Job		
Total B						
Total A+B						
SGST @ 9%						
CGST @ 9%						
Say Total						
Grand Total						


P.L. Hadule

Deputy Engineer

Mechanical Subdivision No.2

Dharashiv