

WORK DETAILS

Name of work : Repair & Reconditioning Boom Cylinder Assly of Tata Hitachi 120 Hydraulic Exc No. 52806

Sr. No.	Part Details		Qty	Rate	Amount		
	Part Number	Description					
	Repair & Reconditioning Boom Cylinder Assly of Tata Hitachi 120 Hydraulic Exc No. 52806 by removing the Boom Cylinder assly from machine, dismantling, checking and removing unserviceable parts & replacing by new spares. Also removing bushing of assly & replacing by new spares as per OEM Specification						
A	Providing & fitting following spares as per OEM Specification						
1	TC01374/39	Seal Service Kit	1	No			
2	TC01374/7	Bushing	1	No			
3	TC01374/8	Bi metal Bushing	1	No			
4	4437282	Hose	1	No			
B	LABOUR CHARGES						
1	Removing Arm/arm/boom jack assly. from machine and refitting after repairs		1	Job			
2	Dismantling of jack assly., cleaning, inspection and replacement of seals with test & trial		1	Job			
3	Cylinder barrel end bushing replacement		2	Job			
4	Removing and Refitting High pressure Hose Assy.		1	Job			
GST 18%							
Total Rs							



Deputy Engineer
Mechanical Subdivision, Latur