

WORK DETAILS

Name of work : *Repair to BEML BL9H-Loader No.10560 by replacing Solenoid Valve & Hoses etc.*

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair to BEML BL9H-Loader No.10560 by replacing Solenoid Valve & Hoses etc. as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	374TNB1041	SOLENOID VALVE	1	No.		
2	474PH03616	HOSE(L=2500)	1	No.		
B	LABOUR CHARGES					
1	Control valve overhauling		1	Job		
2	Removing and refitting high pressure hose assembly		1	Job		
					GST 18%	
					Total Rs	



**Deputy Engineer
Mechanical Subdivision, Latur**