

Work Details

Name of Work : Repair & reconditioning to rear Suspension assly, starter assly, electrical system & servicing to the vehicle
Tata Xenon Yodha MH 25 BE 2275.

Sr. No.	Particulars		Qty		Rate	Amount
1	2	3	4	5	6	7
	Repair & reconditioning to rear Suspension assly, starter assly, electrical system & servicing to the vehicle Tata Xenon Yodha MH 25 BE 2275 by removing unservicable parts & replacing with new parts as per OEM specifications.					
A	Cost of Spares Charges					
1	289732600104	ASSY.REAR SHOCK ABSORBER	2	No		
2	289832407109	8TH LEAF	1	No		
3	265115109907	SWITCH ASSY	1	No		
4	289654400102	ASSY H/L WITH BLINKER-RH RHD	1	No		
5	289654400101	ASSY H/L WITH BLINKER LH RHD	1	No		
6	265954410123	5-FUNCT E CERT.T/L.W/ E MK.BULB LH	1	No		
7	265954410124	5-FUNCT E CERT.T/L.W/ E MK.BULB RH	1	No		
8	278918130104	ASSY OIL FILTER	1	No		
9	254709110106	ASSY FUEL FILTER (MICO)	1	No		
10	253409130254	AIR FILTER ASSY	1	No		
11	282647600139	ASSY HOSE - AIR FILTER OUTLET	1	No		
12	89432400103	LEAF ASSLY WITH BUSH	2	No		
13	253450110243	RADIATO CORE WITH FAN	1	No		
	Cost of Spares Rs :					
B	Cost of Labours					
1	Rear spring leaf assly. Removing dismantling, recambering and refitting / Assly. SU/02		7	Job		
2	Replacing new radiator core by removing and refitting the top and bottom. E/49		1	Job		
	Cost of Labour Rs :					
	Cost of Spares + Labour Rs :					
	CGST @ 9% Rs :					
	SGST @ 9% Rs :					
	Grand Total Rs :					
	Round Off Rs :					



(S.S. Garad)

Deputy Engineer

Mechanical Sub Division No.3,

Dharashiv