



कार्यकारी अभियंता, यांत्रिकी विभाग क्रमांक २, पुणे ३७ यांचे कार्यालय

दूरध्वनि/फॅक्स क्रमांक ०२०-२४२६६०११.सांकेतांक - १२०० E-mail : eemd123@gmail.com

डाक प्रमाणित सह

यांवि-२/ यंत्र दुरुस्ती / दरपत्रक / तां-३ / २६६७ / २०२४

प्रति,
मागील पानावरील यादीप्रमाणे

कार्यकारी अभियंता,

यांत्रिकी विभाग, क्र.२, पुणे ३७

दिनांक - १२/१२/२०२४

या हिताची झॅक्सिस २२० एक्स्केव्हेटर क्र. २२० अ.क्र. ३१२ च्या दुरुस्ती कामाकरिता

दरपत्रक मागविणेबाबत.

महाशय,

.उप अभियंता, यांत्रिकी उप विभाग, पंढरपूर यांचे अखत्यारीतील विषयांकीत कामांसाठी

यांत्रिकी संघटनेकडे नोंदणीकृत अभिकरणांकडून सिलबंद लिफाफ्यात सोबत जोडलेल्या कामाचा तपशिल व नियम व अटनुसार दरपत्रक मागवण्यात येत आहेत. दरपत्रकाच्या सिलबंद लिफाफ्याच्या वरील बाजुस दरपत्रक असा उल्लेख करून उपरोक्त विषयाचा व या कार्यालयाचा उपरोक्त पत्र क्रमांक नमुद करण्यात

यावा. सदरचे दरपत्रक हे दिनांक- १२/१२/२४ रोजी ठीक ४.०० वाजेपावेतो या कार्यालयांस प्राप्त होणे

आवश्यक आहे.दरपत्रकामधिल दर हे दरपत्रक उघडल्यापासून १२० दिवस बंधनकारक राहतील.

कोणतेही एक अथवा सर्व दरपत्रके स्विकारण्याचा अथवा नाकारण्याचा अधिकार राखून

ठेवण्यात येत आहे.

आपला विश्वासु

सोबत :-कामाचा तपशिल

कार्यकारी अभियंता

यांत्रिकी विभाग, क्र.२, पुणे ३७

यांना माहिती व योग्य त्या कार्यवाहीसाठी

'अग्रेषित.


प्रत- .उप अभियंता, यांत्रिकी उप विभाग, पंढरपूर

प्रत- . भांडार शाखा विभागिय कार्यालय,यांना माहिती व योग्य त्या कार्यवाहीसाठी .

Schedule

Name of Work :- Repairs to Tata Hitachi ZX220 Sr.No.- 0312 by way of replacing following spares as per O.E.M. specification and part nos.with cost of material and labour charges etc.complete job

Sr. No.	Description	QTY.	unit	Rate	Amount
Repairs to Tata hitachi Zaxis 220-0312 by way of replacing cost of spares and labour charges as per OEM specification					
A Spares					
1	4712342 COUPLING	1	NO		
2	YA60016317 HOSE	1	NO		
3	9264581 HOSE	1	NO		
4	XB00009459 GLASS	1	NO		
5	XB3656/13 PACKING RUBBER	1	NO		
6	TD03656/12 TRACK BOLT	12	NO		
7	TD03656/13 TRACK NUT	12	NO		
TOTAL B1					
GST @18%=					
Total B1					
B LABOUR CHARGES B3					
1	OIL COOLER CLEANING WITH PLATE PACKING	1	JOB		
2	RADIATOR CHOCK UP REMOVING BY CLEANING ALL THE TUBES SOLDERING THE TUBES WITH TOP & BOTTOM REMOVING AND REFITTING	1	JOB		
3	REMOVING HIGH PRESSURE HOSE ASSEMBLY	2	JOB		
4	REMOVING GROUSER SHOE BOLTS BY GAS CUTTING & REFITTING OF GROUSER SHOE WITH NEW SHOE BOLTS / SHOE	3	JOB		
Total Labour					
GST @18%=					
Total B3 Rs.=					
Total B1 + B3					
SAY Rs. =					


Executive Engineer,
Mechanical Division No. 2,
Pune - 37