

WORK DETAILS

Name of work : Repair & Reconditioning To Main piping Assly of Tata Hitachi EX350 No 0402

Sr. No.	Part Details		Qty	Rate	Amount
	Part Number	Description			
	Repair & Reconditioning To Main piping Assly of Tata Hitachi EX350 No 0402 by removing the assly from machine, dismentling cheking and removing unservicable parts & replacing by new spares Also removing busing of bucket link assly& Replacing by New spares as per oem specification				
A	Providing & fitting following spares as per OEM Specification				
1	4345675	HOSE	3	No	
2	4386290	HOSE	1	No	
3	9163651	HOSE	1	No	
B	LABOUR CHARGES				
1	Removing and refitting high pressure hose assembly		5	Job	
					GST 18%
					Total Rs



Deputy Engineer
Mechanical Subdivision, Latur