

# Work Details

Name of work : Supplying & Fitting Top side cabin Glass for TATA Hitachi Zx120H No 52466.

Sr. No.	Part Details		Qty/Unit		Rate	Total
	Part Number	Description				
	Repairs to Tata Hitachi Zx120H No 52466 by way supplying & Fitting glass as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	4602564	Glass	1	No		
2	4602565	E Glass Green	1	No		
<b>Total of Spares Rs.</b>						
<b>B</b>	<b>Labour Chaggess</b>					
1	BD/09	Door glass regulator machine replacing / Door Equivalent to Tata Prima	2	No		
<b>Total of Labour Rs :</b>						
<b>Total ( Spares + Labour ) Rs :</b>						
<b>CGST 9% :</b>						
<b>SGST 9% :</b>						
<b>Grand Total Rs :</b>						
<b>Round Off Rs :</b>						



**(S.S.Garad )**  
 Deputy Engineer  
 Mechanical Subdiv.No.3,  
 Dharashiv