


Work Details

Name of work : Repairs to Hydraulic System of TATA Hitachi 120 H Ex No. 52466.

Sr. No.	Part Details		Qty / Unit		Rate	Total
	Part Number	Description				
	Repairs to Hydraulic System of TATA Hitachi 120 H Ex No. 52466. by way supplying Hoses as per OEM Specification & part number given below.					
A	Cost of Spares Charges					
1	4332827	Hose	1	No		
2	4455157	Hose	1	No		
3	9149507	Hose	1	No		
4	4455222	Hose	1	No		
5	4455198	Hose	1	No		
Total of Spares Rs.						
B	Labour Chaggas					
1	Removing & refitting high pressure hose assly.		5	No		
	Total fo Labour Rs :-					
	Total of Spares + Labour Rs :-					
	CGST 9%					
	SGST 9%					
	Grand Total Rs :-					
	Round Off Rs :-					



(S.S.Garad)
Deputy Engineer
Mechanical Subdivision No. 3,
Dharashiv