


## Work Details

Name of work : Supplying & Fitting Top side cabin Glass for TATA Hitachi Zx120H No 51573.

Sr. No.	Part Details		Qty/Unit	Rate	Total	
	Part Number	Description				
	Repairs to Tata Hitachi Zx120H No 51573 by way supplying & Fitting glass as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	4602564	Glass	1	No		
2	4602565	E Glass Green	1	No		
	<b>Total of Spares Rs.</b>					
B	<b>Labour Chagges</b>					
1	Door glass regulator machine replacing / Door Equivalent to Tata Prima		2	No	484.00	
	<b>Total of Labour Rs :</b>					
	<b>Total ( Spares + Labour ) Rs :</b>					
	<b>CGST 9%</b>					
	<b>SGST 9%</b>					
	<b>Grand Total Rs :</b>					
	<b>Round Off Rs :</b>					



( G.S.Giram)

**Deputy Engineer**

Mechanical Subdivision (LTP),  
Latur