



कार्यकारी अभियंता, यांत्रिकी विभाग क्रमांक २, पुणे ३७ यांचे कार्यालय
दूरध्वनि/फॅक्स क्रमांक ०२०-२४२६६०११.संकेतांक - १२०० E-mail : eemd123@gmail.com

डाक प्रमाणित सह

यांवि-२/ यंत्र दुरुस्ती / दरपत्रक / तां-३ / ५४९ / २०२३

कार्यकारी अभियंता,

यांत्रिकी विभाग, क्र.२, पुणे ३७

दिनांक - 14/02/2024

प्रति,

मागील पानावरील यादीप्रमाणे

टाटा टिप्पर MH १४ CL १५२५ च्या दुरुस्ती कामाकरिता
दरपत्रक मागविणेबाबत.

महाशय,

.उप अभियंता, यांत्रिकी उप विभाग, **टॅभूर्णी** यांचे अखत्यारीतील विषयांकीत कामांसाठी

यांत्रिकी संघटनेकडे नोंदणीकृत अभिकरणांकडून सिलबंद लिफाफ्यात सोबत जोडलेल्या कामाचा तपशिल व नियम व अटनुसार दरपत्रक मागवण्यात येत आहेत. दरपत्रकाच्या सिलबंद लिफाफ्याच्या वरील बाजूस दरपत्रक असा उल्लेख करून उपरोक्त विषयाचा व या कार्यालयाचा उपरोक्त पत्र क्रमांक नमुद करण्यात

यावा. सदरचे दरपत्रक हे दिनांक- रोजी ठीक ४.०० वाजेपावेतो या कार्यालयांस प्राप्त होणे

आवश्यक आहे.दरपत्रकामधिल दर हे दरपत्रक उघडल्यापासून १२० दिवस बंधनकारक राहतील.

कोणतेही एक अथवा सर्व दरपत्रके स्विकारण्याचा अथवा नाकारण्याचा अधिकार राखून

ठेवण्यात येत आहे.

आपला विश्वासु

सोबत :-कामाचा तपशिल

कार्यकारी अभियंता

यांत्रिकी विभाग, क्र.२, पुणे ३७

यांना माहिती व योग्य त्या कार्यवाहीसाठी

'अग्रेषित.


प्रत- .उप अभियंता, यांत्रिकी उप विभाग, **टॅभूर्णी**

प्रत- . भांडार शाखा विभागिय कार्यालय,यांना माहिती व योग्य त्या कार्यवाहीसाठी .

Schedule

Name of work :- Repairs to 1613 Tata Tipper MH 14 CL 1525

Sr. No.	Description	Quantity	Rate	Amount
A	Cost Of Spares			
1	3521801610 OIL FILTER	1	No.	
2	5737810021 FILTER ELEMENT	1	No.	
3	9450030118 FUEL FILTER SFC	1	No.	
4	9450030205 WATER SEPARATOR	1	No.	
5	9450030209 STRAINER ASSY	1	No.	
	206732107132 Second Leaf	2	No.	
	206732107133 Third Leaf	2	No.	
Total Rs				
GST @ Rs 18%				
B1 Total Rs				
Labour Charges				
1	Wheel alignment	1	Job	
2	Oil filter replacing	3	Job	
3	Branding on vehicle & front & rear number plate, stop plate painting	0	Job	
4	Removing radiator, fan, guard etc & refitting to machine after repairs	1	Job	
5	Clutch unit complete dismantling, cleaning, checking, overhauling by replacing	1	Job	
6	Steering unit overhauling	1	Job	
7	Front axle beam bush bore reaming	1	Job	
8	Alternator overhauling & refitting	1	Job	
9	Starter overhauling	1	Job	
	Front Spring leaf assy removing , dismantling recambering and refitting / assy	2	Job	
Cost Of (B3)=				
GST@ 18%				
Total Cost of Material Rs.(B3)=				
Grand Total (B1 +B3) =				
Say Rs. =				


Executive Engineer,
Mechanical Division No. 2,
Pune - 37