WORK DETAILS

Name of work: Repair to Travel & Front Piping of Tata Hitachi Zx120-52806.

Sr. No.	Part Details		_			
	Part Number	Description	Qty		Rate	Amount
	Repair to Travel & Front Piping of Tata Hitachi Zx120-52806 by way of supplying Following Spare parts as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	4447483	HOSE	1	No.		
2	4260127	HOSE	1	No.		
3	4259322	HOSE	1	No.		
В	LABOUR CHARGES					
1	Removing and refitting high pressure hose assembly		3	Job		
GST 18%						
Total Rs						

Deputy Engineer Mechanical Subdivision, Latur