


INQUIRY

Name of work :- Repair to JCB JS-140 Excavator No.2439381 by way of supplying Hose, Fan, Turbocharger, pin & washer etc.

Sr. No.	Part No.	Description	Qty	Unit	Rate	Amount
	Repair to JCB JS-140 Excavator No.2439381 by way of supplying Hose, Fan, Turbocharger, pin & washer etc. as per OEM Specification etc complete					
A	Cost of Spares Charges :					
1	KMV0932	Hose	1.00	No.		
2	JNV0070	Hose	1.00	No.		
3	4080727	Fan	1.00	No.		
4	4035721	Turbocharger	1.00	No.		
5	229/01303	PIN	3.00	No.		
6	229/01304	LOCKING WASHER	4.00	No.		
Total						
Add GST @ 18%						
Total A- Material Cost						
B	Cost of Labour Charges :					
1	(E/56)	Silencer/muffler repairing by removing, cleaning and refitting with welding work	1	Job.		
	(E/68)	Removing radiator, fan, guard etc and refitting to machine after repairs.	1	Job.		
2	(H/06)	Removing & refitting high pressure hose assly	2	Job.		
Total						
Add GST @ 18%						
Total B- Labour Cost						
Total Amount Material + Labour						
Say Rs.						



(G. S. Giram)
Deputy Engineer,
Mechanical Sub Division(L.T.P.),
Latur