Name of Work :- Repair to sliding type 0.9x0.9 M Head Regulator Gate and canal gates of various sizes of Isapur Milia under Executive Engineer, Akola Irrigation Division, Akola.

SARSH MARKET STREET, CANSO	ABSTRACT				
Sr. No.	Description	Q	Quantity Rat		Amount
A)	Repair to 0.9x0.9 m Head Regulator of Isapur M. I. Tank				
1	Providing and supplying Single Thrust ball Bearing 51217 - 2 No. of Hoist of Head regulator of size 0.9 x 0.9 Mtr. Complete with cost of				
	material, sundry material and labour charges. (RA - 1) i) SKF Single Thrust Ball Bearing 51217 - 2 Nos	1	No		
2	Cleaning of square threaded and v- threaded portion of Stem rods by	1	No	3524.90	3524.90
	Cleaning agent and applying M. P. Grease to threaded portion of Canal Gate of size 0.90 x 0.90 Mtr - 1 No. Complete with cost of material and labour charges. (RA-2)			2453.2	9131.14
3	Providing and applying anticorrosive coal tar black paint IS290-1961 in two coats including surface preparation, chipping the welding, cleaning spatters, dust etc. Complete as directed. (RA-3)	1	No	9131.14	9107.14
B)	Repair to Canal Outlets of Isapur M. I. Tank				-
	Repair to Canal Outlets Size 0.3x0.3 Mtr				21050 10
i)	Dismantlling of Stem Rod, Hoist & Skin Plate by Gas cutting and refitting of same of Canal Gate of size 0.3 x 0.3 Mtr to 0.5 x 0.5 Mtr - 1 No. Complete with cost of sundry material and labour charges. (RA - 4)	16	No	3853.15	30023·2
ii)	Replacement of New stem rod of 32 mm dia - 1.5 Mtr long - 1 No. of	16	No	<u>(2398.75</u>	(38380.00)
,	Canal Gate of size 0.3 x 0.3 Mtr to 0.5 x 0.5 Mtr Complete including cost of material and machining charges. (RA - 5)		1	1876-95	
iii)	Replacement of Stem nut for 32 mm dia stem rod of Canal Gate of size 0.3 x 0.3 Mtr to 0.5 x 0.5 Mtr Complete including cost of material and machining charge (RA - 6)	16	No	(3111.31) 330J.33	(49781.03) 57 950 · 24
iv)	Dismantalling and fitting Phosphor Bronze Guide Bush - 2 No. of Hoist of Canal Gate of size 0.3 x 0.3 Mtr. Complete with cost of material, sundry material and labour charges (RA - 7)	16	No	1143.83	18301.20
v)	Repair to Hoist Body by fabrication & Erection of new hoist assembly with bearing housing for canal gate of size 0.3x0.3 M canal gate (RA - 8)	16	No //	(4040 12) 2576-53	64641 93 ; 4763).84 .
vi)	Anti corrosive Painting of Gate Assembly size 0.3 x 0.3 mtr (RA - 9)	16	No	638.25	10211.98
C)	Transportation From Akola to Isapur Minor Project by 7.5 MT cap Truck 1 trip (RA- 10)	1	trio	5*29,79	5129,79
	2,57134.SC Tot				
	7171.48 46231.96 3.66.41.23	Add 1 %		ce Charges:	2805,48
Say:					333852.00

¹⁾ Rates of Material are taken as per Schedule of Rates for WRD CSR 2022-23, Mech CSR 2023-24, PWD SSR 2023-24 and as per Prevailing Market Rate.

2) Rates of steel section as per JPC January 2025.

U. J. Khole

Sectional Engineer Verified & Recommended 19. Gate Manufacturing & Erection

Sanction to Rs 333852

(R. G. Thakare) Deputy Engineer

Subdivision No. 2, Akola

sanctioned Estimate No

EE/MD/AK/2015.... 9; ... _

Sarction Rs 306041/- CThese lakh

Executive Engineer Mechanical Division Akola

six thousand fourtings , _ only