

Schedule - B

Name Of Work :- Repairs to LH side of track motor of L&T 72 Hydraulic Excavator Sr. No. 997

Sr.N	Description	Qty	Rate	Amount	
1	Removing and refitting of track motor (A/10)	1	2651	2651	
2	Overhauling of track motor by dismantling, cleaning and inspection of parts, reassembling (A/11)	1	2651	2651	
3	Repair to LH side of track motor of L&T 72 hydraulic excavator Sr. No. 997 by Replacing the following spares				
3.1	00835904R	Piston ring	20	152	3040
3.2	01226505H	Wear plate	20	191	3820
3.3	00836307E	Circlip	20	19	380
3.4	01639942V	Roller bearing assembly	20	1413	28260
3.5	05146212J	Plug kit	12	791	9492
3.6	30030001F	Arbor	1	25623	25623
3.7	30046229U	Cover kit	1	11027	11027
				Total Rs :-	86944
				GST @18% Rs :-	15649.92
				Total Rs :-	102593.92
				Say Rs :-	102594.00

Rupees In Words : One Lack Two Thousand Five Hundred Ninety Four Only

Executive Engineer
Mechanical Division, Osmanabad