

Name of Work : Repairs to Pressure line and Replacing Hydraulic Hoses (Swing Line) of JCB JS-140 Excavator No. 2439381

Sr. No.	Description	Qty	Unit	Rate	Amount
	Repairs to Pressure line and Replacing Hydraulic Hoses (Swing Line) of JCB JS-140 Excavator No. 2439381 by way removing damaged parts from pressure line & Hydraulic hose as pr O.E.M. specificaton and part No.given below.				
A	Cost of Spare Charges:				
1	333-P1847	Solenoid station	1	No	
2	627-10362	Hose	1	No	
3	627-10363	Hose	1	No	
4	627-10484	Hose	1	No	
Total A:					
B	Cost of Labour Charges:				
1	H/05	Labour charges for control valve overhauling	1	Job	
2	H/06	Removing & refitting Non hidden high pressure hoses	3	Job	
Total B:					

Note: Mention the quoted rates are of inclusive GST charges or exclusive GST charges clearly.


Executive Engineer

Mechanical Division, Osmanabad


Mechanical Division, Osmanabad