



महाराष्ट्र शासन
जलसंपदा विभाग

कार्यकारी अभियंता, यांत्रिकी अभियांत्रिकी कर्मशाळा विभाग, नागपूर

जलसंपदा विभागाच्या संकेतस्थळास कृपया भेट द्या -
<https://wrd.maharashtra.gov.in>

जावकक्र. 2804 / यांअकविना/लेखा.१/२०२४

E-mail : eemewdngp@yahoo.in Phone No. 0712-2981048

GST : 27AAAGE0001N2ZT

कार्यकारी अभियंता, यांत्रिकी अभियांत्रिकी कर्मशाळा विभाग,
सदर, लिंक रोड नागपूर-४४०००१ यांचे कार्यालय

दिनांक : १०/१०/२०२५

प्रति,

मा.जिल्हा माहिती अधिकारी,
जिल्हा माहिती कार्यालय,
जिल्हा वर्धा

विषय :- वर्गीकृत वृत्तपत्रात निविदा सूचना क्र.१८(दुसरी वेळ)/२०२५-२६ प्रकाशित करण्याबाबत.

संदर्भ :- १) महाराष्ट्र शासन सामान्य प्रशासन विभाग शासन निर्णय क्रमांक मावज-२०१८/प्र.क्र.३४८/३४ मंत्रालय मुंबई दिनांक २०-डिसेंबर २०१८.
२) या विभागाचे जावक पत्र क्र.२१२९/यांअकविना/लेखा-निविदा सुचना क्र.१८/२०२५-२६ दि.२१.०८.२०२५

पत्रासोबत जोडलेली जाहिरात वृत्तपत्रात प्रकाशित करण्यात यावी ही विनंती.

१	मुळ कार्यालयाचे नाव व पत्ता	कार्यकारी अभियंता, यांत्रिकी अभियांत्रिकी कर्मशाळा विभाग, सदर नागपूर-४४०००१ दूरध्वनी क्र. ०७१२-२५३४६८५ Email- eemewdngp@yahoo.co.in
२	जाहीरात प्रकाशित करण्याची अंतीम तारीख	१७/१०/२०२५ पूर्वी
३	जाहीरातीचे स्वरूप प्रसारीत करण्याचा प्रकार	“लघु” संवर्गातील एक दैनिक व “लघु” संवर्गातील एक साप्ताहिक
४	ज्या जिल्ह्यात कामे आहे त्या जिल्ह्याचे नाव	वर्धा जिल्हा
५	जाहीरात देयक कोणाला सादर करावयाचे आहे त्याचे नाव	कार्यकारी अभियंता, यांत्रिकी अभियांत्रिकी कर्मशाळा विभाग, सदर नागपूर-४४०००१
६	जाहीरातीचा आकार	निर्धारित मापदंडात (कमीत कमी दरात व आकारात)
७	जाहिरात किती वेळेस प्रसिध्दीस द्यावी	फक्त एकाच वेळेस
८	जाहिरात शिफारस करण्यात आलेली वृत्तपत्र	नियमाप्रमाणे

(लेखाशिर्षावरील अनुदान कमी मिळत असल्यामुळे निर्धारित मापदंडात कमीत कमी दरात व आकारात प्रसिध्दी करण्यात यावी जेणे करुन देयकाचे भुगतान करणे साईचे होईल)

सहपत्र : निविदा सुचना - तीन प्रतित

(वि.स.प्रधान)

कार्यकारी अभियंता

यांत्रिकी अभियांत्रिकी कर्मशाळा

विभाग, नागपूर

प्रत - मा. अधीक्षक अभियंता, यांत्रिकी मंडळ, नागपूर यांना माहितीसाठी सविनय सादर.

प्रत - भांडारा शाखा / विभागीय कार्यालय सुचना फलकावरील व्यापक प्रसिध्दीसाठी.

महाराष्ट्र शासन
जलसंपदा विभाग

कार्यकारी अभियंता, यांत्रिकी अभियांत्रिकी कर्मशाळा विभाग, नागपूर
E-mail : eemewdnngp@yahoo.in

Phone No. 0712-2981048

निवीदा सुचना क्र. - १८ (दुसरी वेळ) / सन २०२५-२६

महाराष्ट्र राज्याच्या राज्यपालांच्या वतीने कार्यकारी अभियंता, यांत्रिकी अभियांत्रिकी कर्मशाळा विभाग, सदर, नागपूर, महाराष्ट्र शासन हे सक्षम निविदाकारांपुढे खालील कामाकरीता निविदा मागवित आहे. महाराष्ट्र शासन जलसंपदा विभाग शासन निर्णय क्रमांक सीकॉर्ण/१११७/प्र.क्र.१०४/१७/यांत्रिकी दिनांक १४.०३.२०१८ अन्वये खालील कामाकरीता निविदा सादर-करणारे कंत्राटदार, जलसंपदा विभागातील यांत्रिकी संघटनेकडे पंजिकृत असणे आवश्यक नाही. सदर निविदा सूचना जलसंपदा (यांत्रिकी) विभागाच्या वेबसाईटवरील क्र. www.mahayantriki.gov.in या संकेतस्थळावर बघायला मिळेल. निविदा स्वीकारण्याचा अथवा नाकारण्याचा अधिकार कार्यकारी अभियंता, यांत्रिकी अभियांत्रिकी कर्मशाळा विभाग, नागपूर, यांनी राखून ठेवला आहे. अट असलेली निविदा स्वीकारली जाणार नाही. सदर निविदा सुचनेमध्ये काही बदल होत असल्यास विभागीय कार्यालयाच्या सूचना फलकावर / www.mahayantriki.gov.in उपलब्ध करून देण्यात येईल.

२) कामाचे नाव : कार नदी प्रकल्प (घा) धरणाचे मुख्य विमोचक सेवादार , आकस्मिक द्वार व Well मधील Air vent pipe व valve दुरुस्ती कामे.

(कोरी निवीदा प्रपत्राची किंमत Rs. १,००० /- (रु. १८०/- Goods and Services Tax (GST) भरणा केलेली पावती निविदा उघडण्याचा दिवसापर्यंत कार्यालयात जमा करणे बंधनकारक राहिल. अन्यथा लिफाफा क्र. १ मध्ये अपात्र करण्यात येईल.)

कामाची किंमत : - रु. 398274/-

जिल्हा : वर्धा जिल्हा

निविदा विक्रीचा कालावधी :- दि. १७.१०.२०२५ (११.०० वाजेपासून) ते दि. २४.१०.२०२५ (१८.०० वाजेपर्यंत)

निविदा सादर करण्याचा अंतिम कालावधी :- दि.१७.१०.२०२५ (११.०० वाजेपासून) ते दि. २७.१०.२०२५ (१८.०० वाजेपर्यंत)

निविदा उघडण्याचा कालावधी :- दिनांक २८.१०.२०२५ १४.०० पासून

कार्यकारी अभियंता, यांत्रिकी अभियांत्रिकी कर्मशाळा विभाग, नागपूर यांच्या कार्यालयात.

जा.क्र. /लेखा शाखा.२/निवीदा सुचना क्र.१८ (दुसरी वेळ)/२०२५-२६ दिनांक

(वि.रा.प्रधान)

कार्यकारी अभियंता

यांत्रिकी अभियांत्रिकी कर्मशाळा विभाग,

नागपूर

प्रत - मा. अधीक्षक अभियंता, यांत्रिकी मंडळ, नागपूर यांना माहितीसाठी सविनय सादर.

प्रत - भांडार शाखा / विभागीय कार्यालय सुचना फलकावरील व्यापक प्रसिध्दीसाठी.

SCHEDULE - B

Name of Work - Repairing of Service Gate (Left) size 1.2 x 1.2 Mtr-1 No. & Emergency Gate-1
No and Bypass valve at Kar project under Executive Engineer, Minor
Irrigation Division, Wardha

Sr. No.	Description of Job	Qty	Unit	Rate	Amount
A	Emergency Gate :-				
1	Gate Leaf Dismantling, Refitting and Lowering after Repairs.				
1	Dismantling of Roller type Gate leaf of size 1.2 x 1.2 Mtr (upto 20 MWH) and hoist assembly - 1 No. lifting of the same up-to Platform for Repair work and lowering on Sill Beam. Complete job including cost of Material (Non consumable) material and labour charges, with leads & lifts at site etc complete.	1	No	26230.71	26230.71
2	Replacement of Side Rubber Seal.				
	Dismantling of Damaged Side Rubber seal - 1 Mtr from Emergency Gate Leaf & fitting of new Musical note type Side rubber seal (confirms to IS: 11855 / 1986 (Updated)) with M-12 x 75 mm long Nut Bolts - 13 Nos (per mtr) Complete job with Material, Sundry material, and labour charges, with leads & lifts at site etc complete. {Total length of Side rubber seal = (Height + 0.200 mtr) @ Kar Project. Brass Cladded Musical Note type Side Rubber Seal 32 mm dia x 105 mm x 16 mm (1200 mm + 200 mm) (1.2+0.2)=1.4 Mtr	1	No	19448.16	19448.16
3	Replacement of Top Rubber Seal.				
	Dismantling of Damaged Top Rubber seal - 1 Mtr from Emergency Gate Leaf & fitting of new Double Stem type Top rubber seal (confirms to IS: 11855 / 1986 (Updated)) with M-12 x 75 mm long Nut Bolts - 13 Nos (per mtr) Complete job with Material, Sundry material, and labour charges, with leads & lifts at site etc complete. {Total length of Top rubber seal = Width + 0.200 mtr} @ Kar Project. Brass Cladded Double Stem type Top Rubber Seal 32 mm Dia x 115 mm x 15 mm {Total length of Top rubber seal = Width + 0.200 mtr} = 1.2 + 0.2 = 1.4 Mtr	1	No	9724.08	9724.08
4	Replacement of Bottom Rubber Seal.				
	Dismantling of Damaged Bottom Rubber seal - 1 Mtr from Gate Leaf & fitting of new Plain Flat type Bottom rubber seal (confirms to IS: 11855 / 1986) with M-12 x 75 mm long Nut Bolts - 13 Nos (per mtr) Complete job with Material, Sundry material, and labour charges, with leads & lifts at site etc complete. {Total length of Bottom rubber seal = Width + 0.200 mtr} Plain Flat type Bottom Rubber Seal 82 mm x 16 mm {Total length of Bottom rubber seal = Width + 0.200 mtr} = 1.2+0.2 = 1.4 mtr	1	No	7341.49	7341.49

Contractor

No. of Corrections

Executive Engineer

5	Track Rollers Dismantling , Refitting and fitting after Greasing.				
	Dismantaling & Cleaning of Track Rollers (4 Nos), of Roller type Gate of size 1.2 x 1.2 Mtr (upto 20 MWH) - 1 No.. Refitting with M.P. Grease 2 Kg. Complete job including cost of sundry material and labour charges, with leads & lifts at site etc complete . (Excluding Cost of New Bearing / Bush, Ref. Jobwork DSR / Bearing price list) SKF Rollar Spherical Bearing (23220 CC/W33) (Ref. pg no. 83 Sr. no. II C(2) of WRD-CSR (Mech) 2023-24)	1	No	68328.52	68328.52
6	Cleaning and applying Cardium compound to Wire Rope of EOT				6862.91
	Removing Old Cardium Compound of wire rope (100 Mtrs) of 8 MT cap EOT - 1 No., by cleaning Agent, Applying new Cardium Compound (Servocoat 140) - 12 Kg. including cost of material, sundry material and labour charges with leads & lifts at site etc complete, as per drawings, specifications and or instructions of concern in charge	1	No	6862.91	
B	Service Gate :-				
7	Gate Leaf Dismantling , Refitting and Lowering after Repairs.				
	Dismantling of Roller type Gate leaf of size 0.9 x 0.9 Mtr / 1.2 x 1.2 Mtr (upto 20 MWH) and hoist assembly - 1 No. lifting of the same up-to Platform for Repair work and lowering on Sill Beam. Complete job including cost of Material (Non consumable) material and labour charges, with leads & lifts at site etc complete .	1	No	26230.71	2630.71
8	Replacement of Side Rubber Seal.				
	Dismantaling of Damaged Side Rubber seal - 1 Mtr from Gate Leaf & fitting of new Musical note type Side rubber seal (confirms to IS: 11855 / 1986 (Updated)) with M-12 x 75 mm long Nut Bolts - 13 Nos (per mtr) Complete job with Material, Sundry material, and labour charges, with leads & lifts at site etc complete . {Total length of Side rubber seal = (Height + 0.200 mtr) PTFE Cladded Musical Note type Side Rubber Seal 32 mm dia x 105 mm x 15 mm {Total length of Side rubber seal = (Height + 0.200 mtr)= 1.2+ 0.2	1	No	24603.60	24603.60
9	Replacement of Top Rubber Seal.				
	Dismantaling of Damaged Top Rubber seal - 1 Mtr from Gate Leaf & fitting of new Double Stem type Top rubber seal (confirms to IS: 11855 / 1986 (Updated)) with M-12 x 75 mm long Nut Bolts - 13 Nos (per mtr) Complete job with Material, Sundry material, and labour charges, with leads & lifts at site etc complete . {Total length of Top rubber seal = Width + 0.200 mtr} PTFE Cladded Double Stem	1	No	12301.80	1231.80

Contractor

No. of Corrections

Executive Engineer

		88			
	type Top Rubber Seal 32 mm Dia x 115 mm x 15 mm (Total length of Top rubber seal = Width + 0.200 mtr) = 1.2 + 0.2				
10	Replacement of Bottom Rubber Seal.				
	Dismantling of Damaged Bottom Rubber seal - 1 Mtr from Gate Leaf & fitting of new Plain Flat type Bottom rubber seal (confirms to IS: 11855 / 1986) with M-12 x 75 mm long Nut Bolts - 13 Nos (per mtr) Complete job with Material, Sundry material, and labour charges, with leads & lifts at site etc complete. (Total length of Bottom rubber seal = Width + 0.200 mtr) Plain Flat type Bottom Rubber Seal 82 mm x 16 mm (Total length of Bottom rubber seal = Width + 0.200 mtr) = 1.2+0.2 = 1.4 mtr	1	No	7341.49	7341.49
11	Straightening of Stem Rod.				
	Straightening of Stem Rod ~ 1 No. of Service Gate of size 1.2x1.2 Mtr by using hydraulic press machine. complete with machinery charges with leads & lifts at site etc complete.. (Excluding cost of material and labour)	1	No	3339.06	3339.06
12	Cleaning of square threaded and v- threaded portion of Stem rods.				
	Cleaning of square threaded and v- threaded portion of Stem rods by Cleaning agent and applying M. P.Grease to threaded portion of Service Gate of size 1.2x1.2 Mtr - 1 No. Complete with cost of material and labour charges with leads & lifts at site etc complete.	1	No	3524.90	3524.90
13	Track Rollers Dismantling , Refitting and fitting after Greasing.				
	Dismantling & Cleaning of Track Rollers (4 Nos), of Roller type Gate of size 1.2 x 1.2 Mtr (upto 20 MWH) - 1 No.. Refitting with M.P. Grease 2 Kg. Complete job including cost of sundry material and labour charges, with leads & lifts at site etc complete. (Excluding Cost of New Bearing / Bush, Ref. Jobwork DSR / Bearing price list).	1	No	17769.94	17769.94
14	Replacement & Refitting of Bye- Pass Valve. Sluice valves - PN -1 dia. 100 mm	1	No	11767.51	11767.51
15	Fabrication & Erection of Allied Parts of Sluice Valve. (Pipe dia OD 100 mm ID 90 mm, Length 800 mm for shaping into Elbow), Flange plate 10mm thk OD 250 mm ID 100 mm -2 nos for join Valve to Elbow)	1	No	2369.08	2369.08
16	Replacement of Air Vent Pipe. (GI Pipe OD 160 mm ID 150 mm L- 4 mtr, Flange plate 10mm thk OD 250 mm ID 160 mm Qty 4 Nos Means Two pairs, Flat 5x25 mm (for making OD 160 mm Clamping Ring)- 4 Nos, Bar dia 10 mm L= 700mm (for Support to Clamping Ring)- 4 Nos)	1	No	10305.92	10305.92

17	Surface Preparation, Providing & Applying anticorrosive coal tar black paint IS 290-1961 in two coats to Service gate size 1.2 x1.2 Mtr-04 No's	30. 18	Sq.m	9140.65	9140.65
18	Cleaning of Emergency Gate size 1.2 x1.2 mtr slot -2 Nos at Kar Project .	2	Nos.	60650.50	121301.00
	Under Water Inspection Charges per day including cost of material, sundry material and labour charges etc. as per drawings, specifications and or instructions of concern in charge. Under Water Inspection Charges using divers upto 25 Mtr depth.				
19	Transportation from Wardha to Kar project by Tata 407 Tempo	2	Trip	5171.20	10342.40
Total In Rs.					398273.93
Say (₹)					398274.00
GST AS PER APPLICABLE					

(In Words Rs. Three Lakh Ninety Eight Thousand Two Hundred & Seventy four Only)

Mocanand
S.M. Kanchan
sect. Engr

Deputy Engineer,
Mech Engg Workshop Sub
Division no.3
Wardha

Shan

Executive Engineer
Mechanical Engineering
workshop Division, Nagpur