oving Old damaged Rubber Seal and Supplying and Fitting New Rubber Seal and Applying Anticorrosive Coal Tar Black Paint to Approch Bridge, Hoist Bridge oving the definition of the components and general maintenance @ khirkund, Tq Akot, Dist. Akola under Under Executive Engineer Akola Irrigation Division, Akola Other allied Components and general maintenance @ khirkund, Tq Akot, Dist. Akola under Under Executive Engineer Akola Irrigation Division, Akola Minos

ABSTRACT

	ABSTRACT				antity	1 4	
	Description					Rate	Amount
Di 8	sme Em	entling of Old damaged Side, Bottom& Top Rubber seal of Service Gate Size 1.2 x 1.2 sergency gate -1.2x1.2m - 2 Nos Supplying and fitting new Suppling and Fitting Side Top Rubber seal As per RA-1	mtr - 2 Nos 2, Bottom&				
A	of (U joi	smantaling of Damaged Side Rubber seal - 1 Mtr from Gate Leaf & fitting new Musical note type Side rubber seal (confirms to IS: 11855 / 1986 lpdated)) with M-[6 x100] mm long Nut Bolts - 13 Nos (per mtr) Complete b with Material, Sundry material, and labour charges, with leads & lifts at the etc complete. {Total length of Side rubber seal = (1.2 + 0.2 = 1.4mtr For both Side= 1.4x2 = 2.8 mtr)	1 No	4.00	No	35201.53	140806.12
В	n (1)	ismantaling of Damaged Top Rubber seal - 1 Mtr from Gate Leaf & fitting of ew Double Stem type Top rubber seal (confirms to IS: 11855 / 1986 Updated)) with M-12 x 75 mm long NutBolts - 13 Nos (per mtr) Complete job with Material, Sundry material, and labour charges, with leads & lifts at site etcomplete. {Total length of Top rubber seal = (1.2 + 0.2 = 1.4mtr)	1 No	4.00	140	33201.33	/
С	fi 1 v	Dismantaling of Damaged Bottom Rubber seal - 1 Mtr from Gate Leaf & tting of new Plain Flat type Bottom rubber seal (confirms to IS: 11855 / 986) with M-12 x 75 mm long Nut Bolts - 13 Nos (per mtr) Complete job with Material, Sundry material, and labour charges, with leads & lifts at site etc.	1 <b>N</b> o	_			
S	trai ten	ghtening of Stem Rod,Cleaning of square threaded and v- threaded portion of rods, Dismantling of Roller type Gate leaf,Dismantaling & Cleaning of Trackers as per RA-2					
A		straightening of stem Rod - 1 NO.of canal gate of size above 0.90x0.90 mtr to 1.5x1.5 mtr by usung hydraulic press machine .complete with machinery charges with leads & lifts at site etc complete. (Excluding cost of material and labour)	1 No				
	в	cleaning of square threaded and v-threaded portion of stem Rods by cleaning agent and applying M.P. Grease to threaded portion of canal gate of size above 0.90x0.90 mtr to1.5x1.5 mtr -1 NO. complete with cost of material and labour charges with leads & lifts at site etc. complete.	1 No	2.00	Job	50864.61	101729.22
	С	Dismantling of roller type gate leaf of size 0.9x0.9 mtr /1.2x1.2 mtr ( up to 20 MWH ) and hoist Assembly -1 No.lifting of the same up-to platfrom for repair work and lowering on sill beam . Complete job including cost of material ( nonconsumable ) material and labour charges, with leads & lifts at site etc complete	1 <b>N</b> o	<i>y</i> *	No		
	D	Dismantaling & cleaning of Track rollers ( 4 Nos ) ,of Roller type gate of size 0.9x0.9M /1.2x1.2 mtr ( upto 20 MWH ) - 01 No. refitting with M.P. Grease 2 kg . Complete job including cost of sundry material and labour charges , with leads & lifts at site etc. complete. ( Excluding cost of new bearing /bush ,ref. jobwork DSR/bearing price List )	1 <b>N</b> o				
Ì	Manufacturing,Providing and supplying , G. M. Nut,C. I. Guide Bracket at Khirkhund MI Tank As per RA-3						
3	Α	Manufacturing ,providing and supplying G.M NUT OD-200,ID -71 L-368 mm	1 No	200	No	77205.03	
	В	Manufacturing , providing and supplying Tapper roller Bearing (32311)-210	1 <b>N</b> o	2.00			154410.05

	A Comment of the Comm	7	1	1	1	- 1
Manufacturing ,providing and supplying C.I Guide Bracket = length of interm. Stem Rod = 2.5 mtr .10 stem Rod pcs for 25m WH -10 pairs	1 No				and the same second and th	
Manufacturing and supplying of worm shaft Dia 120 I 950 mm		2.00	No	38477.30	76954.60	
viding and applying anticorrosive coal tar black paint IS 290-1961 in two coats uding surface preparation, chipping the welding, cleaning spatters, dust etc. nplete as directed, to Approch Bridge, Hoist Assembly and Other Allied		2.00	(Job)	(31956.00) 28832	63912.01	76
abrication and Fitting of Railing to Approch Bridge and fitting chequrired plate at Mi Tank Khirkhund Project as per RA-5		2.00	No	58678.05	117356.10	
nsportation Charges from site upto District headquarter Akola to Khirkhund al 160 km .As per rate analysis 06	1	2.00	Trip	8208.00	7 (16416.00)	82
657	129.3	Add 1	1% Insurar	Total: nce Charges:	671584.10 6715.84	7
1182	83-3	2.16	Ade	d 18% GST :- Say :	120885.14 799185.00	

Rate of steel are as per JPC Market Price retail for 1st oct 2024

Rate of painting and rubber seal are as per Common schedule of rates 2023-24 and 2022-23 of Water resources departmet (Government of Maharashtra)

The required Materials and skilled labours for such type of work are not available within the division, Hence the above work is proposed for outside agency.

(S.S.Chavhan)
Assistant Engineer II

ASSISTANT ENGINEER II

Deputy Engineer

Gate Manufacturing and Erection

Sub-Dn. No. 1 Akola

Sanctioned Estimate: No
EE/MD/AK/2025... Ph.
Sanction for Rs 7,81,984/- (Seven latch eighty one
thousand Nine Hundred ... only Eighty four only

Executive Engineer Mechanical Division Akola