

WORK DETAILS

Name of work : Repair & Reconditioning LH Lower Track Roller Assy of JCB JS 140 Hyd Exc No 2439384

Sr. No.	Part Details		Qty	Rate	Amount		
	Part Number	Description					
	Repair & Reconditioning LH Lower Track Roller Assy of JCB JS 140 Hyd Exc No 2439384 by removing the assly from machine,dismantling , checking and removing unservicable parts & replacing by new spares . Also removing bushing of LHLower Track Roller Assy & replacing by new spares as per OEM Specification						
A	Providing & fitting following spares as per OEM Specification						
1	331/42460	LOWER Track Roller	2	No			
2	624/80025	Hose	2	No			
B	LABOUR CHARGES						
1	Dismantling Track chain by removing Master Pin / Master Link bolts.		1	Job			
2	Track roller removing from chassis and refitting/No		2	Job			
3	Reaseembling track chain by fitting master pin		1	Job			
4	Removing and Refitting High pressure Hose Assy.		2	Job			
GST 18%							
Total Rs							



Deputy Engineer
Mechanical Subdivision, Latur