

WORK DETAILS

Name of work : Repair to Pilot (11), Return (1) & Drain Piping of Tata Hitachi Zx120-52473.

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair to Pilot (11), Return (1) & Drain Piping of Tata Hitachi Zx120-52473 by way of supplying Following Spare parts as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	4460593	HOSE	1	No.		
2	7037064	PIPE	1	No.		
3	4430533	HOSE	1	No.		
4	9194322	HOSE	1	No.		
5	4187308	O-ring	2	No.		
B	LABOUR CHARGES					
1	Removing and refitting high pressure hose assembly		4	Job		
GST 18%						
Total Rs						



**Deputy Engineer
Mechanical Subdivision, Latur**