

Enquiry

**Name of work : Providing &Fitting Hoses of Arm cylinder,Bucket Cilynder
Line group of BEMI BE-200 excavator No.10076.**

Sr. No.	Description		Qty	
	Repairs to Arm cylinder line Group (Attachment piping) & Bucket cylinder line group (Attachment piping) of BEMI BE-200 excavator No.10076 by removing old damaged and leakages Pipe Assly. From machine and replacing and fitting following Pipe Assly. as per O.E.M. specification and part No. Given below.			
A	Cost of Spares Charges			
1	781PH02506	1. Pipe Assly.Arm cylinder line Group	1	Nos
2	781PH02514	2. Pipe Assly. Arm cylinder line Group	1	Nos
3	781PH02458	3. Pipe assly. Bucket cylinder line group	1	Nos
B	Cost of Labour Charges			
4	(H/06)	Cost of labour charges removing and fitting above pipe Assly. to machine with test and trial	3	job



G.S.Giram
Deputy Engineer
Mech. Sub Division (L.T.P)
Latur