


Work Detail's

Name of work :- Repair & Reconditioning to Main Piping & Working Assembly of Sany 140 Excavator
No.14381161

Sr. No.	Description	Qty	Unit	Rate Rs	Amount
1	2	3	4	5	7
	Repair & Reconditioning to Main Piping & Working Assembly of Sany 140 Excavator No.14381161 by repairs to following spares parts as per OEM Specification of given below.				
A	Cost of Spares Charges				
1	12625300	steel pipe assembly of bucket cylinderSY	1	No.	
2	12625262	Steel Pip Assy Arm Cyl SY135C9I2K.3.1.1	2	No.	
3	B230103007775	Rubber Hose 4SP20-DKOS90-SFL90-1050-V0Q/	1	No.	
4	B230103006437	Rubber Hose 4SP20-DKOS45-DKOS90-950-V90Q	1	No.	
5	B230103003627	Rubber hose	1	No.	
6	B230103006436	Rubber Hose 4SP16-DKOL-DKOL90-800Q/SY110	1	No.	
7	13309205	Intake Hose	1	No.	
	Total of Spares Rs :-				
B	Cost of Labour Charges				
1	H/06 Removing & refitting high pressure hose assly.		5	Job	
	Total of Labour Rs :-				
	Total Spares+Labour Rs :-				
	CGST 9 % Rs :-				
	SGST 9 % Rs :-				
	Grand Total Rs :-				
	Round Off Rs :-				


 (P.L.Hadule)
Deputy Engineer
 Mechanical Subdivision No. 2,
 Dharashiv