

Work Detail's

Name of work :- Repairs To Under Carrage Hydraulic System (Track Motor) Rear Flange Assly (RH Side) Of Sany 140 Excavator No.14381161

Sr. No.	Description	Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6
	Repairs To Under Carrage Hydraulic System (Track Motor) Rear Flange Assly (RH Side) Of Sany 140 Excavator No.14381161 following spares parts as per OEM Specification of given below.				
A	Cost of Spares Charges				
1	60082995 O-Ring	1	No.		
2	60231647 RELIEF Valve ASSEMBLY	1	No.		
3	12625300 steel pipe assembly of bucket cylinderSY	1	No.		
4	12625262 Steel Pip Assy Arm Cyl SY135C9I2K.3.1.1	1	No.		
5	60320473 PIPE S/A-RE (RH) CWM144105E02	1	No.		
6	60320474 PIPE S/A-CE(RH) CWM144105E03	1	No.		
7	B230103003627 Rubber Hose	1	No.		
8	B230103000282 Rubber Hose 1 SN12-DKOL-DKOL90-1900	1	No.		
9	B210780001310 Connector, Pipe	1	No.		
10	B21078000172 Connector, Pipe	1	No.		
11	A820205002283 Connector	1	No.		
12	B210780001426 Connector	1	No.		
	Total of Spares Rs :-				
B	Cost of Labour Charges				
1	A/10 Removing & refitting of track motor	1	Job		
2	H/06 Removing & refitting high pressure hose assly	2	Job		
	Total of Labour Rs :-				
	Total Spares+Labour Rs :-				
	CGST 9 % Rs :-				
	SGST 9 % Rs :-				
	Grand Total Rs :-				
	Round Off Rs :-				

(P.L.Hadule)
Deputy Engineer
Mechanical Subdivision No. 2,
Dharashiv