Work Details

Name of work: Providing & fitting spares by new one for replacement of damaged items of Sany 140 Excavator No.14381211

Sr. No.	Description		Qty	Unit	Rate	Amount
1	2	3	4	5	6	7
A	Providing & Fitting following spares as per part no & suitable to sany 140 Excavator No.14381161 as per OEM specification given below.			11		
1	11902151K	ClipsSY235C812K.3B.4B-9	2	No		
2	11902148K	Bucket Tooth SY235C8I2K.4B- 3SY235C8I2K	5	No	A The State of the	
3	12657353P	Bucket Tooth Point Adapter	. 5	No	17.0	4
4	60213378	Rubber Hose	2	No		. 4
		•			Total A:	i.
В		Cost of Labour Charges		* .		¥
1	Labour Charges for Repair excavator (A/14)	s to Bucket by replacing the teeth for	5	Job		
Totatl B						ļ
Total A+B: CGST @ 9%						4
						·
SGST @ 9%					6	
	6	1 1 1 w 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		生化品	Total:	
				0.000	Grand Total:	

P.L. Hadule

Deputy Engineer Mechanical Subdivision No.2

Dharashiv