

# Work Details

Name of work :- Repairs To Air Intake System Assy Of Sany 140 Excavator No.14381211

| Sr. No. | Description                                                                                                                         | Qty | Unit | Rate, Rs | Amount |
|---------|-------------------------------------------------------------------------------------------------------------------------------------|-----|------|----------|--------|
| 1       | 2                                                                                                                                   | 3   | 4    | 5        | 6      |
|         | Repairs To Air Intake System Assy Of Sany 140 Excavator No.14381211 following spares parts as per OEM Specification of given below. |     |      |          |        |
| A       | Cost of Spares Charges                                                                                                              |     |      |          |        |
| 1       | A22900003104 Clamp                                                                                                                  | 1   | No.  |          |        |
| 2       | 13861292 Long Air Intake Tube                                                                                                       | 1   | No.  |          |        |
| 3       | A22900004579 T-hoop fl117.4-fl125.4                                                                                                 | 1   | No.  |          |        |
| 4       | 1380205 Intake Hose                                                                                                                 | 1   | No.  |          |        |
| 5       | 60029642 Fuel Sensor DX-YWS-04                                                                                                      | 1   | No.  |          |        |
| 6       | 60320473 PIPE S/A-RE (RH) CWM144105E02                                                                                              | 1   | No.  |          |        |
| 7       | 60320474 PIPE S/A-CE(RH) CWM144105E03                                                                                               | 1   | No.  |          |        |
| 8       | A210608000074 O-Ring                                                                                                                | 2   | No.  |          |        |
|         | Total of Spares Rs :-                                                                                                               |     |      |          |        |
| B       | Cost of Labour Charges                                                                                                              |     |      |          |        |
| 1       | H06 Removing & refitting high pressure hose assy                                                                                    | 1   | Job  |          |        |
| 2       | E/46 Radiator check up removing by cleaning all the tubes, soldering the tubes with top & bottom removing and refitting             | 1   | Job  |          |        |
|         | Total of Labour Rs :-                                                                                                               |     |      |          |        |
|         | Total Spares+Labour Rs :-                                                                                                           |     |      |          |        |
|         | CGST 9 % Rs :-                                                                                                                      |     |      |          |        |
|         | SGST 9 % Rs :-                                                                                                                      |     |      |          |        |
|         | Grand Total Rs :-                                                                                                                   |     |      |          |        |
|         | Round Off Rs :-                                                                                                                     |     |      |          |        |

(P.L.Hadule)  
Deputy Engineer  
Mechanical Subdivision No. 2,  
Dharashiv