

Work Detail's

Name of work :Repairs to Boom Cylinder Assly of Sany 140 Excavator No.14381211

Sr. No.	Description		Qty	Unit	Rate	Amount
1	2	3	4	5	6	7
A	Repairs to Boom Cylinder Assly of Sany 140 Excavator No.14381211 as per OEM specification given below.					
1	60320544	BUSH RH Side	1	No		
2	60280063	Grease Nippleprotection Cap RH Side	4	No		
3	60320474	Pipe S/A-CE(RH) CWM144105E03	1	No		
4	60320456	Pipe S/A-CE(RH) CWM144105E04	1	No		
5	60320530	Pipe S/A-RE(LH) CWM144105E05	1	No		
6	60320544	BUSH LH Side	1	No		
7	60280063	Grease Nippleprotection Cap LH Side	4	No		
8	60295017	Seal Kit Boom	2	No		
9	B230103005402	Rubber Hose 4SP20-DKOS-SFL90-1800Q/SY110	2	No		
					Total A:	
B	Cost of Labour Charges					
1	Removing bucket/arm/boom jack assly. from machine and refitting after repairs H/08		1	Job		
2	Radiator chock up removing by cleaning all the tubes, soldering the tubes with top & bottom removing and refitting E/46		1	Job		
3	Removing & refitting high pressure hose assly. H/06		1	Job		
					Totalt B	
					Total A+B:	
					CGST @ 9%	
					SGST @ 9%	
					Total:	
					Grand Total:	


P.L. Hadule
Deputy Engineer
Mechanical Subdivision No.2
Dharashiv