


Work Details

Name of work :- Repair & Reconditioning To Main Piping of Sany 140 Excavator No.14381211

Sr. No.	Description	Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6
	Repair & Reconditioning To Main Piping of Sany 140 Excavator No.14381211 by repairs to following spares parts as per OEM Specification of given below.				
A	Cost of Spares Charges				
1	B230103000069	Rubber Hose	1	No.	
2	B230103005717	Rubber Hose 4SP20-DKOS-SFL-580Q/SY	4	No.	
3	A210204000196	Screw M10x20GB70.1	2	No.	
4	A820205002474	Connector G3/4-M36S-L80 SY 130.1.2-19	8	No.	
5	60205580	Check Valve LV-12-25	1	No.	
6	A820199000360	Block PT	1	No.	
7	B230103001642	Suction Hose Pipe	1	No.	
Total of Spares Rs :-					
B	Cost of Labour Charges				
1	H/06 Removing & refitting high pressure hose assly.		6	Job	
2	E/45 Oil cooler cleaning with plate packing		1	Job	
3	E/46 Radiator chock up removing by cleaning all the tubes, soldering the tubes with top & bottom removing and refitting		1	Job	
Total of Labour Rs :-					
Total Spares+Labour Rs :-					
CGST 9 % Rs :-					
SGST 9 % Rs :-					
Grand Total Rs :-					
Round Off Rs :-					


 (P.L.Hadule)
Deputy Engineer
 Mechanical Subdivision No. 2,
 Dharashiv