


Work Detail's

Name of work :- Repair & Reconditioning to Pilot Piping Of Tata Hitachi Zx 220 No. 306

Sr. No.	Description		Qty	Unit	Rate Rs	Amount
1	2	3	4	5	6	7
	Repair & Reconditioning Engine Cntrol Unit Of TATA Hitachi Zx 220 No. 306 following spares parts as per OEM Specification of given below.					
A	Cost of Spares Charges					
1	4427357	HOSE	1	No.		
2	3103187	PIPE	1	No.		
3	4639989	PIPE	1	No.		
4	3103186	PIPE	1	No.		
5	4632041	HOSE	1	No.		
6	4219363	HOSE;NYLON	1	No.		
7	4630946	HOSE	1	No.		
8	A852122	ADAPTER;S-7/16-20	9	No.		
9	Z957366	O RING (Offer 957366)	1	No.		
10	4438888	PIPE (Alt Part A852422)	2	No.		
11	4452733	HOSE	1	No.		
12	4427351	HOSE	1	No.		
13	4630947	HOSE	1	No.		
14	4630949	HOSE	1	No.		
15	A852322	ELBOW;S	1	No.		
16	Z957366	O RING (Offer 957366)	4	No.		
17	4255304	FITTING;PIPE	5	No.		
18	A885002	DUMMY PLUG	1	No.		
19	4293950	ELBOW;S	1	No.		
20	A852334	ELBOW;S	1	No.		
21	962567	O-RING(4509180)	1	No.		
22	A852244	ELBOW;S	1	No.		
23	9735305	CLAMP	2	No.		
24	9735306	CLAMP	2	No.		
25	4452733	HOSE	1	No.		
26	4427351	HOSE	1	No.		
27	4630947	HOSE	1	No.		
28	4630949	HOSE	1	No.		
29	4642231	HOSE	1	No.		
30	4213401	HOSE	1	No.		
31	4634380	HOSE	1	No.		
32	A852133	ADAPTER;S	2	No.		
33	962567	O-RING(4509180)	1	No.		
34	A852333	ELBOW;S	1	No.		
Total of Spares Rs :-						0.00

B	Cost of Labour Charges			
1	H/06 Removing & refitting high pressure hose assly.	15	Job	
	Total of Labour Rs :-			
	Total Spares+Labour Rs :-			
	CGST 9 % Rs :-			
	SGST 9 % Rs :-			
	Grand Total Rs :-			
	Round Off Rs :-			


 (P.L.Hadule)
Deputy Engineer
 Mechanical Subdivision No. 2,
 Dharashiv