

WORK DETAILS

Name of work : Repair & Reconditioning Bucket Cylinder assly of JCB JS 140 No 2439384

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair & Reconditioning Bucket Cylinder assly of JCB JS 140 No 2439384 by removing the Bucket Cylinder assly from machine,dismentling the cylinder jack checking and removing unservicable parts & replacing by new spares . Also removing bushing of bucket link assly & replacing by new spares as per OEM Specification					
A	Providing & fitting following spares as per OEM Specification					
1	335/B6920	Spare Seal Kit	1	No.		
2	332/Y7033	Bush Cushioning head end	1	No.		
3	550/41935	NUT Piston Rod	1	No.		
4	550/43351	Bush	1	No.		
5	KNV0484	PIN Attachment	2	No.		
6	KNV0485	PIN Attachment	1	No.		
B	LABOUR CHARGES					
1	Removing bucket/arm/boom jack assly. from machine and refitting after repairs		1	Job		
2	Dismantling of jack assly., cleaning, inspection, reconditioning to damaged portion of jack piston rod, cromium plating and replacement of seals with test & trial		1	Job		
GST 18%						
Total Rs						



Deputy Engineer
Mechanical Subdivision, Latur