

Work Details

Subject :- Providing & Fitting Engine support i.e. Engine Foundation of Tata Hitachi 120 H No. 51578

Sr. No.	Part No.	Description	Qty	Unit	Rate	Amount
1	2	3	4	5	6	7
	Providing & Fitting Engine support i.e. Engine Foundation of Tata Hitachi 120 H No. 51578 by removing old, damaged engine foundation as per OEM specification given below					
A	Cost of Spares					
1	8064364	BRACKET (ISUZU ENGINE)	1	No.		
2	8064357	Bracket-Engine	1	No.		
3	4609020	BOLT;SEMS	7	No.		
4	4334526	Rubber	2	No.		
5	J950014	NUT;M14 X 2	4	No.		
6	4426636	Rubber (Old -4448738)	2	No.		
7	4428242	STOPPER	2	No.		
8	4366699	STOPPER	2	No.		
9	4426637	Rubber (Old - 4448739)	2	No.		
10	J921612	BOLT M16X170	1	No.		
11	4437177	BOLT M16X260	1	No.		
12	J950016	NUT M16X2	2	No.		
	Total A :					
B	Cost of Labour					
1	Engine foundation replacing per No. (E/40)		4	Job		
2	Oil cooler cleaning with plate packing (E/45)		1	Job		
3	Complete wiring and loom making (EL/05)		1	Job		
	Total B Rs :					
	Total A+ B Rs :					
	CGST 9 % Rs :					
	SGST 9 % Rs :					
	Grand Total Rs :					
	Round Off Rs :					



(S.S.Garad)

Deputy Engineer

Mechanical Subdivision No. 3,
Dharashiv