

WORK DETAILS

Name of work : Repairs to Mahindra Bolero pickup MH25P4692 by way of supplying filters ,Hoses, Clutch assy,Leaf spring front & rear Assy. etc.

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repairs to Mahindra Bolero pickup MH25P4692 by way of supplying filters ,Hoses, Clutch assy,Leaf spring front & rear Assy. etc. as per OEM Specification & part number given below.					
A	Providing & fitting following spares as per OEM Specification					
1	0801CA0032N	CLUTCH COVER ASSY	1	No.		
2	0801BA0285N	CLUTCH DRIVEN PLATE ASSY(F491)	1	No.		
3	0706AD1730N	BOTTOM LEVER MAXX	1	No.		
4	0706AAD02270N	GEAR SHIFT LEVER	1	No.		
5	0313AB1960N	AIR FILTER ASSEMBLY	1	No.		
6	0313AAB02510N	HOSE ASSY AIR CLEANER (CLEAR SIDE)	1	No.		
7	0313AC0280N	AIR ELEMENT	1	No.		
8	9420000073	OIL FILTER CARTRIDGE (OPTIONAL	1	No.		
9	1001CAA15521N	FUEL FILTER ASSY	1	No.		
10	1001FAA00561N	TANK MODULE ASSY DELPHI	1	No.		
11	0401AAA02680N	LEAF SPRING ASSY REAR	1	No.		
12	0402BA0281N	SHOCK ABSORBER REAR	1	No.		
13	0401ACG00010N	LEAF SPRING ASSY FRONT	1	No.		
B	LABOUR CHARGES					
1	Clutch unit complete dismantling, leaning, checking, overhauling by replacing necessary parts		1	Job		
2	Front spring leaf assly. Removing, dismantling, recambering and refitting / Assy.		1	Job		
3	Rear spring leaf assy. removing, dismantling, recambering and refitting / Assy.		1	Job		
4	Shock absorber fitting / No.		2	Job		
5	Complete flooring rusted portion cutting and new flooring pieces patching & welding including material		1	Job		
6	Removing & refitting high pressure hose assembly(Similar to excavator)		1	Job		
					GST 18%	
					Total Rs	



Deputy Engineer
Mechanical Subdivision, Latur