

**WORK DETAILS**

**Name of work : Repairs & reconditioning to Boom Assly. & Boom Cylinder Assly. of JCB JS 140 Hydraulic Excavator No. 2439384.**

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repairs & reconditioning to Boom Assly. & Boom Cylinder Assly. of JCB JS 140 Hydraulic Excavator No. 2439384 by dismantling from machine, checking & removing unservicable parts & removing worn out bushes & replacing by new parts as per OEM Specification.					
A	Providing & fitting following spares as per OEM Specification					
1	811/90376	PIN	1	No.		
2	811/90468	PIN PIVOT	1	No.		
3	KNV0473	COLLAR SET	1	No.		
4	KHV0100	SEAL DUST	4	No.		
5	6009/3825Z	BOLT	1	No.		
6	6009/3827Z	BOLT	1	No.		
7	173R020VZ	NUT;HEX (LPS)	4	No.		
8	JNV1577	BUSH	2	No.		
9	JNV1414	SHIM	2	No.		
10	332/K5138	BUSH (EMS)	2	No.		
11	KNV0487	LOCK RING	1	No.		
12	KNV0488	PIN ATTACHMENT	1	No.		
B	<b>LABOUR CHARGES</b>					
1	Cylinder barrel end bushing replacement		4	Job		
2	Silencer/muffler repairing by removing, cleaning and refitting with welding work		1	Job		
					<b>GST 18%</b>	
					<b>Total Rs</b>	



**Deputy Engineer  
Mechanical Subdivision, Latur**