WORK DETAILS

Name of work: Repair & Reconditioning Hose Assemblies of Main Piping 3 & 4 of Tata Hitachi 120 Hyd Exc No. 52473

Sr. No.	Part Details			_		
	Part Number	Description	Qty		Rate	Amount
	Repair & Reconditioning Hose Assemblies of Main Piping 3 & 4 of Tata Hitachi 120 Hyd Exc No. 52473by removing the assly from machine, dismentling checking and removing unservicable parts & replacing by new spares . Also removing bushing of bucket link assly & replacing by new spares as per OEM Specification					
A	Providing & fitting following spares as per OEM Specification					
1	4333700	Hose	1	No.		
2	4333699	Hose	1	No.		
3	4192047	Hose	1	No.		
4	4425161	Hose	1	No.		
В	LABOUR CHARGES					
1	Removing & refitting high pressure hose assembly			Job		
GST 18%						
Total Rs						

Deputy Engineer Mechanical Subdivision, Latur