## **Work Details**

Name of work: Repairs & reconditioning to bucket jack assly.of L & T Ck72 No.997

			_			
Sr. No.	Part Details  Repairs & reconditioning to bucket jack assly.of L & T Ck72  No.997		Qty / Unit		Rate	Total
A	Cost of Spares					
1	300228631	Crome Bush	2	Nos.		
2	302496395	Seal Kit	1	Nos.		
				Cost	of Spares Rs :	
В	Cost of Labour					
1	Removing bucket/arm/boom jack assly. from machine and refitting after repairs. (H/08)		1	Job		
2	Dismantling of jack assly., cleaning, inspection and replacement of seals with test & tria. (H/09)		1	Job		
	Cost of Labour Rs:					
	Total of (Spares + Labour) Rs:					
	CGST @ 9% Rs :					
	SGST @ 9% Rs :					
	Grand Total Rs :  Round Off Rs :					
	Round Off Rs :					

- Zumlis

(S.S.Garad)

Deputy Engineer

Mechanical Subdivision No. 3,

Dharashiv