


## INQUIRY

**Name of work :-** Repair and reconditioning Hydraulic System by removing and refitting filters & hoses to BEML BE-200 Excavator No. 10076

Sr. No.	Part No.	Description	Qty	Unit	Rate	Amount
	Repair and reconditioning Hydraulic System by removing and refitting filters & hoses to BEML BE-200 Excavator No. 10076 as per OEM Specification etc complete					
<b>A</b>	<b>Cost of Spares Charges :</b>					
1	781HS02035	Filter	1.00	No.		
2	781PH02928	Filter: Pilot	1.00	No.		
3	799PH02805	Hose Assly R.H.	1.00	No.		
4	799PH02813	Hose Assly L.H.	1.00	No.		
5	155EG12242	Hose; Clamp	2.00	No.		
<b>Total</b>						
Add GST @ 18%						
<b>Total A- Material Cost</b>						
<b>B</b>	<b>Cost of Labour Charges :</b>					
1	(E/67)	Complete servicing of machine at periodic interval of 250/500/1000 working Hours including applicable changing of fuel filter, engine oil filter, filters of hydraulic, transmission, steering system etc.	1	Job.		
2	(H/06)	Removing & refitting high pressure hose assly.	2	Job.		
<b>Total</b>						
Add GST @ 18%						
<b>Total B- Labour Cost</b>						
<b>Total Amount Material + Labour</b>						
<b>Say Rs.</b>						



(G. S. Giram)  
Deputy Engineer,  
Mechanical Sub Division(L.T.P.),  
Latur