

WORK DETAILS

Name of work : Repair & reconditioning Center Joint assembly of Tata Hitachi Zaxis 120 Hydraulic Excavator No. 52806

Sr. No.	Part Details		Qty		Rate	Amount
	Part Number	Description				
	Repair & Reconditioning Center Joint Assly Assly of Tata Hitachi Excavator Zaxis 120 Sr No 52806 by Center Joint Overhauling by dismantling , overhauling & re fitting with replacing seal ,O Ring , bushing etc to machine complete job					
A	Providing & fitting following spares as per OEM Specification					
1	4410066	BUSHING	1	No		
2	4410446	'O' RING	1	No		
3	4406165	SEAL OIL	6	No		
4	4410445	SEAL DUST	1	No		
5	3070250	RING	1	No		
6	A810100	'O' RING	1	No		
7	J010816	Bolts SEMS	3	No		
8	2034607	COVER	1	No		
B	LABOUR CHARGES					
1	Center Joint Overhauling		1	Job		
					GST 18%	
					Total Rs	



**Deputy Engineer
Mechanical Subdivision, Latur**