


Work Details

Name of work :Repairs To Drive Belt & Pulley & TURBOCHARGER Of JCB JS 140 No. 2439381.

Sr. No.	Part Details		Qty/Unit	Rate	Total	
	Part Number	Description				
	Repairs To Drive Belt & Pulley & TURBOCHARGER Of JCB JS 140 No. 2439381 by removing TURBOCHARGER assly. from machine cleaning,inspecting all parts and removing damaged spares and refitting assly. to machine by using new as per O.E.M.specification and part No.given below .					
A	Providing & fitting following spares as per OEM					
1	332/Y3355	TURBOCHARGER	1	No		
2	333/Y9499	PULLEY, CRANKSHAFT	1	No		
4	4900/10015	Belt	1	No		
	Total of Spares Rs.					
B	Labour Chagges					
1	E/68	Removing radiator, fan, guard etc and refitting to	1	Job		
3	E/52	Turbocharger dismantling for repairs and refitting	1	Job		
	Total of Labour Rs :					
	Total (Spares + Labour) Rs :					
	CGST 9%					
	SGST 9%					
	Grand Total Rs :					
	Round Off Rs :					



(G.S.Giram)

Deputy Engineer

Mechanical Subdivision (LTP),
Latur