

ENQUIRY

Name of work : Repairs to Hydraulic System of BEML BE-200 Ex.No.10076

Sr No	Description	Qty	Unit	Rate	Amount
	Repairs to Hydraulic System of BEML BE-200 Ex.No.10076 by removing old wornout and damaged pipe assly./Hose assly.Inspecting, & replacing damaged parts as OEM Specifications and part No.given below.				
1	Pipe Assly. R.H. 781PH02417	1	No.		
2	Pipe Assly. R.H. 781PH02433	1	No.		
3	Pipe Assly. 781PH02474	1	No.		
4	Pipe assly.781PH02936	1	No.		
5	Pipe assly.781PH02409	1	No.		
6	Hose 781PH91129	2	No.		
7	Hose 781PH91112	3	No.		
Total Cost of Spares Rs.					0.00
GST 18% on Spare parts					0.00
(A) Total cost of spares including GST					0.00
5	Removing & refitting high Pressure Hoses/Pipe assly.(H/06)	10	No.		
(B) Cost of Labour Rs.					0.00
GST 18%					0.00
(B) Total cost of Labour including GST					0.00
(A+B) Grand Total Rs.					0.00
Say Rs.					



(G.S.Giram)

Deputy Engineer
Mechanical Sub Division (LTP),
Latur